EXHIBIT 12

Paul Varghese 30B6 Crowley Govenment Services Provence, Tiffany N v. United States of America, et al

	Page
IN THE UN	ITED STATES DISTRICT COURT
FOR THE I	DISTRICT OF SOUTH CAROLINA
CI	HARLESTON DIVISION
	IN ADMIRALTY
TIFFANY N. PROVI	ENCE, AS THE
PERSONAL REPRESI	ENTATIVE OF
THE ESTATE OF JU	JAN ANTONIO
VILLALOBOS HERNA	ANDEZ,
Pla	intiff,
VS.	CASE NO. 2:21-cv-965-RMG
UNITED STATES OF	F AMERICA,
CROWLEY MARITIME	Ξ
CORPORATION, CRO	DWLEY
GOVERNMENT SERV	ICES, INC.,
DETYENS SHIPYARI	
HIGHTRAK STAFFI	NG, INC. D/B/A
HITRAK STAFFING	, INC.,
Defe	endants.
CONTINUED	
30(b)(6) ZOOM	
DEPOSITION OF:	CROWLEY GOVERNMENT SERVICES, INC
	BY: PAUL VARGHESE
	- 01 000
DATE:	June 21, 2022
	10.05
TIME:	10:07 A.M.
	0.551
LOCATION:	Offices of
	Crowley Maritime Corporation
	9487 Regency Square Boulevard
	Jacksonville, FL
TAKEN BY:	Counsel for the Plaintiff
REPORTED BY:	Wanda K. Cecil
	Certified Court Reporter
	(Appearing by Zoom)

June 21, 2022

Page 10 lifeboat equipment, the davit was the ship 1 2. equipment. Okay. So the lifeboat and the lifeboat 3 Ο. davit was ship's equipment; is that correct? 4 5 Α. That is correct. All right. But the welding machine 6 Ο. 7 that -- any welding machine that Detyens brought on 8 board was shipyard equipment; correct? 9 Α. That is correct. 10 Ο. All right. And any cranes that Detyens 11 might have used that were based on the pier or not 12 part of the ship would have been shipyard equipment; 13 correct? That is -- that is correct. 14 Α. 15 Ο. Okay. And the safety management system 16 that Crowley had developed and that applied to the 17 LUMMUS, had that been reviewed by an outside third 18 party and certified or approved by an outside third 19 party? 20 Yes. Α. 21 And who was that outside third party Ο. 2.2 that approved the safety management system in place 23 on the LUMMUS? 2.4 Α. American Bureau of Shipping. 25 Q. Okay. And in the safety management

June 21, 2022

Page 39 as reflected on Exhibit 2; is that right? 1 2. Α. That is correct. 3 Okay. And then it says on Exhibit 0. Number 2, the crew is assisting DSI with services, 4 safety tag outs and identification of work items? 5 That is correct. 6 Α. 7 Ο. You see that? Yes, sir. 8 Α. 9 Q. All right. Where it says safety tag 10 outs, would that be from the vessel systems or do 11 you have any idea what that's referring to? 12 Α. That's a tag out of the vessel systems. 13 Ο. Okay. And so give us some examples of 14 what kind of systems the crew would be working on 15 tag outs with? 16 If the shipyard -- if the shipyard was working on the lifeboat, the crew would assist them 17 to tag out the lifeboat. If the crew and the 18 19 shipyard is working on the main engine, the crew 20 will work to tag out the main engine. If the 21 shipyard is working on the steering system, the crew 2.2 will work with the shipyard to tag out the steering 23 system. Some examples. 2.4 Ο. Sure. And in the examples you gave,

lifeboats, main engine and steering system, these

2.5

Page 40 are all ship systems that the crew would assist 1 2. Detyens in tagging out? Do I understand that 3 correctly? That is correct. 4 Α. 5 MR. YOUNG: All right. Let me get to the next exhibit. All right. Yes. Exhibit Number 6 7 3, Wanda and Ryan, is Vessel Defendants 1601 through If you can get that in front of Mr. Varghese. 8 1603. 9 It was Number 7, I think, in Ken Fisher's 10 deposition. 11 MR. GILSENAN: Hang on. 12 (EXHIBIT 3, Crowley, Vessel Safety 13 Management System Manual, Bates Stamped 14 Vessel Defendants 1601 through 1604, was marked for identification.) 15 16 THE WITNESS: Yes, sir, I got it. 17 BY MR. YOUNG: 18 Mr. Varghese, we're going to mark as 0. 19 Exhibit Number 3 these couple of pages from the 20 Crowley safety management safety manual. Do you see 21 that? 2.2 Α. Yes. 23 Okay. And this is a part of the safety 0. 24 management system that Crowley produced and was certified by the ABS like you testified about a 25

Paul Varghese 30B6 Crowley Govenment Services June 21, 2022

Page 70 item was 601, caused Detyens to work on the davit, 1 2. engine part on the davit. And they executed that 3 using their, you know, their expertise on that. It was not Crowley's management system applied there. 4 5 Crowley's management system applied lock out/tag out and Crowley executed that. 6 7 BY MR. YOUNG: Yes, sir. I'm not asking about any of 8 Ο. 9 those things. I'm asking about whether there was 10 stored energy in the way in which the davit arm was 11 restrained. 12 MR. GILSENAN: Objection. Asked and 13 answered. 14 MR. YOUNG: Not answered. 15 THE WITNESS: That is the shipyard 16 because -- it was the shipyard responsibility 17 because it was a work item tasked to them. 18 BY MR. YOUNG: 19 Yes, sir. I'm not asking about Ο. 20 anybody's responsibility. I'm asking whether or not 21 there was stored energy in the manner in which the 2.2 davit arm was restrained by Detyens. 23 MR. GILSENAN: Objection. 2.4 BY MR. YOUNG: 2.5 Ο. Yes or no?

Paul Varghese 30B6 Crowley Govenment Services June 21, 2022

Page 118 is -- that is the intent of writing this like that. 1 And in the davit repairs, how did 2. Ο. Okay. 3 Crowley tell the shipyard to do the work? We told the shipyard to restrain the 4 Α. 5 davit arm when the falls are removed and conduct the repairs and then reinstall the falls and bring the 6 7 boat back. That is in Specification 601. Ο. And what is the MSC general technical 8 9 requirement guidance on how to instruct the shipyard to do the work? 10 11 Α. Give the intent of work, general design 12 of the work. Not to tell them how to do their job. 13 Ο. Okay. And let's go back to how Crowley 14 tagged out the lifeboat davit system as a whole in 15 order to support the shipyard. Where was the first 16 tag out? 17 The first tag out normally at the Α. control room, where the main breaker is. 18 19 In the engine control room? Ο. 20 Engine control room. Α. Yes. 21 Okay. And where is the second tag out? 0. 2.2 Α. That is located at the operating station 23 where the lifeboats are operated, lower and raise. 2.4 Out on the deck? Ο. 2.5 Α. Yeah. It's on the deck.